UNCLASSIFIED

AD NUMBER AD355388 **CLASSIFICATION CHANGES** TO: unclassified restricted FROM: **LIMITATION CHANGES** TO: Approved for public release, distribution unlimited FROM: Controlling Organization: British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008.

AUTHORITY

DSTL, ADM 227/2335, 23 Jun 2008; DSTL, ADM 227/2335, 23 Jun 2008

FAULT CARRYING CAPACITY - SANTON 200A ADMIRALTY TYPE ROTARY SWITCH, (U)

ADMIRALTY ENGINEERING LAB WEST DRAYTON (UNITED ...

25 SEP 1964

RESTRICTED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

NOTICE:

THIS DOCUMENT CONTAINS INFORMATION
AFFECTING THE NATIONAL DEFENSE OF
THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE LAWS, TITLE 18,
U.S.C., SECTIONS 793 and 794. THE
TRANSMISSION OR THE REVELATION OF
ITS CONTENTS IN ANY MANNER TO AN
UNAUTHORIZED PERSON IS PROHIBITED
BY LAW.

8 00

CONDITIONS OF REL

This information is disclosed only for official nee by the recombinate No. 2423/3776/1 2 5 SEP 1964 Government and such of its contractors, under seal of sequence,

as may be engaged on a defence project. Disclosure to any other

Covernment or release to the Press or in any other way would be

a breach of these conditions.

The information should be sufeguarded under rules designed to give the state standard of scentity as that maintained by Hes Majessy's to account in the United Kingdom.

The recipe at is warned that information contained in the Ensument may be subject to privately-owned rights. ELECTRICAL DEPARTMENT


ATALOGED BY DDC

ALTY ENGINEERING LABORATORY

WEST DRAYTON, MIDDLESEX

FAULT CARRYING CAPACITY - SANTON 2000 MILELATY TYOU ROTALY S ITCH.





Copy No.

RESTRICTED

CONFIDENTIAL MODRIED HANDLING AUTHORIZED REPORT INC. 2423/3776/1

This document is the property of Her Majesty's Government. It is for the information of officers and responsible officials. The officer or official in possession of this document will be responsible for its safe custody and for ensuring that its contents ero not disclosed to any unauthorised person.

DATE: 2 5 SEP 1964

This document must be kept under lock and key when not in actual use. Any loss or destruction must be reported immediately to the issuing authority through the normal chemnels.

*Mais document contains information affecting the Mational Defense of the United States within the account of the Replement Removed From Title 10, U. C. C. De Cita 753 and 774. Its transmission of the contents in any memor to an unadimental and all prohibited by law."

ELECTRICAL DEFARTURET,

AUNIRALTY ENGINEERING LABORATORY,

MEST DRAYBON, HIDDX.

FAULT CARRYING CAPACITY - SAFFOR 200% AURIRALPY TYPE ROTLLY S ITCH.

Investigator: H.H.J. Button

21. 13.16 Head of Section

Auth rised

Head of Electrical Department

A.E.L.

CR.



RESTRICTED
RESTRICTED HANDLING AUTHORIZED

SULTARY

An investigation was made into the ability of a 200A Triple Pole Santon Retary Switch, Admir. By Type, to carry heavy fault currents until they were cleared by the overload release of a feeder brocker. The tests described in this report are of the nature of a 'go' - 'no go' variety, and were made with direct current. The maximum safe current was found to be of the order of 10 000A at 628v D.C. (closing).

No attempt was made to strip and inspect the smitch between $\tilde{\gamma}$ tests.



FAULT CARRYING CAPACITY - SANTON 2004 TRIMEDPOLE AMIRALTY

TYPE SCITCH

Introduction

This type of switch is already in use in the service, normal type tests having been carried out under E.I.2989. Tests to explore the capacity of the switch to carry large fault currents, until cleared by a feeder breaker, however, had not been made. This is of greater importance, now that fault levels in ships are higher, and it became necessary to know if these switches need fuse protection. Tests were conducted, using direct current and were vitnessed by Mr. S.H. Wardell of V/171/S.

2. Requirements

The maximum time of operation of a feeder breaker was given as 0.25s, and it was required to know the highest current that the switch could be closed on, and carry for this period of time. Tests on a 440V a.c. supply were called for, but heavy current supplies were not available. Direct current was therefore used in accordance with Paragraph 4(d) of the initiating memorandum. amendment to this clause required d.c. tests to be conducted at a voltage equivalent to the peak a.e. voltage of a 440V a.e. supply. It was also laid down that the smitch should be rotated 1000 times in each direction on no load, prior to the current tests.

Description of Switch

The Santon 200A Triple Pole S itch is a quick make/quick break, rotary action switch, with self aligning Rotor-mounted silver plated sliding contacts engaging with prirs of spring loaded silver plated fixed centacts. The type used in this investigation had been developed for Admiralty service.

Whilst tests on Santon 200A Triple Pole Rotary Switch Type H2036. HA79 was specifically asked for, this was not possible without unacceptable delay. Instead, tests were carried out on a makers reconditioned 2001 Triple Pole Switch Type H2026 HA10, which happened to be available.

The HA79 and HA10 types of switch are of similar design, differing only in the number of pales, and in the arrangement of contacts.

Tost Rig

The switch was mounted unenclosed as shown in Fig. 1, and the batteries of the test station were grouped to supply 628V. Connections were made to allow current to flow through the 2 pairs of contacts (2 moving, 2 fixed) in series, which formed one way or "coll" of the switch. Resistances were arranged to give prospective currents of about 5000A, 10 000A, 15 000A and 20 000A, but no industance was added to the test circuit, and the time constants were of the order of 0.004s. As the time of application was 0.25s, the current rese to the full prosective level in each test. Although not specified in the requirements, it was decided to differentiate between especity for "through", and for "closing" current. For the former test the switch was closed under open circuit conditions, the foult breaker being closed subsequently to complete the circuit, and remaining closed for 0.25s. For the latter test the fault breaker was initially closed, and the Santon switch was closed by hand (For safety precautions see Fig. 1). The fault breaker was set to open 0.25s after the Santon switch was closed.



5. Tosts

It was agreed to apply "thr ugh current" and "closing current" tests consecutively, at increasing levels of fault current. All switching operations were made in one direction only, namely clockwise. The same pair of contacts were used for the first six tests, since very little damage was sustained up to Test No. 5. Tests 1 to 7 revealed the approximate leads at 628V at which the switch would fail, and the results are listed in Table 1. The condition of the contacts are shown in Figs. 2. Oscillograms of current flowing, against a time base are shown in Figs. 3 and 4. The d.c. equivalent, (628V), of the peak voltage of an a.c. supply at 440V R.M.S. was used. To determine if the application of 440V D.C., i.e. the equivalent to the R.M.S. value, had a less severe effect, at the same current, Test No. 8 was made. Unused contacts were connected for this test, but the switch feiled as before, unfortunately no oscillogram was obtained in this case.

6. Rosults of Through Current Tosts

Tests 1,3 and 5 indicated that the switch would carry 15 000A for the required time, with slight pitting of the contacts, which would not prevent normal use. Records shown in Fig. 3(a) (b) and (c) prove that the current was uniform, without arcing. Test No. 7 showed that a current of 20 000A would destroy the contacts. This is backed up by the oscillograms shown in Fig. 3(d) which shows the current decreasing as the contacts heat up, followed, after an interval of 0.16s, by violent arcing.

7. Results of Closing Current Tests

Tests 2 and 4 indicate that the switch could be closed on a prespective fault current of 10 000A, and carry this consistently for the required time. This is confirmed by oscillograms shown in Fig. 4(a) and (b). In Test No. 6, the switch was closed on a prespective current of 15 000A, and arcing occurred which reactically destroyed the contacts. Fig. 4(c) shows a slight decrease of current as the contacts became hot, followed, after 0.09s, by violent arcing.

8. Analysis of Results

No sign of mechanical parting, due to magnetic effect, of the contacts was apparent from the oscillograms taken when the switch carried current successfully for 0.25s, Fig. 3(a) (b) and (c). Fig. 4(a) and (b). The two cases in which the switch failed, show a gradual decrease of current until the contacts begin to arc, probably as a rosult of developing hot spots, Fig. 3 (d) and Fig. 4(c). This condition may have been accelerated in the second case when the switch was closed on the fault current, by initial pitting of the contacts. If failure of the contacts was due solely to heating, this effect would be the same for a given current and conditions, either a.c. or d.c. It would be advisable to verify this by some comparative a.c. tests, and these will be undertaken as soon as plent is available.

9. Conclusions

From the limited number of tests possible, with only one switch available, it would appear that,

(a) The 200A Senton Switch Typo H2026 HA10 will carry a through current of 15 000A for 0.25s, without serious damage, but 20 000A applied for the same period will destroy the contacts.

..../(b)

- (b) The minimum current which the switch can be closed on, and corry for this period, without discuss is 10 000A.
- (c) The incidence of croins, following heating of the contacts, determined the fault carrying capacity of the switch, and this should be the same for a.c. and d.e; but tests with a.c. may be necessary to investigate may other effects.
- (d) here foult levels in excess of 10 000A are possible, fuse protection for these 200A Retary Switches is deemed necessary.

TABLE 1


FAULT CARRYING CAPACITY - SAFTOR 200A ARTHRALTY TYPE SHITCH

List of tosts

Test No.	Supply (V)	Type of Test	Prospective Current (A)	Rosult
1	628	Through current	5440	No effect
2	. "	Make	,	; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ; ;
3	11	Through	10 000	Slight sticking of contacts.
4	11	Hake		11 11 11
5	11	Through current	15 900	Slight effort needed to separate contacts which were quite free afterwards
6	11	iiaka	n l	Contacts burst completely away, flesh ever to Earth.
7		Through current	19 700	Contacts practically burnt away.
e	440	Make	14 950	ti ii ii ii

FIG.I.

FAULT CARRYING CAPACITY - SANTON 200A ADMIRALTY TYPE SWITCH.



REPORT NO. 2423/3776/I.


FIG. 3.

FAULT CARRYING CAPACITY - SANTON 200A ADMIRALTY TYPE SWITCH.

OSCILLOGRAMS OF CURRENT
SWITCH CARRYING FAULT CURRENT FOR 0.254.




(a) 5440 A



(b) 10,000 A



(c) 15,800A



(d) 19,700A -- -- -0.16s ----- -> 14,700A

TIME INTERVAL 0.005.


REPORT No. 2423/3776/1.

FIG. 4.

FAULT CARRYING CAPACITY - SANTON 200A ADMIRALTY TYPE SWITCH.

OSCILLOGRAMS OF CURRENT.

SWITCH CLOSING ON, AND CARRYING FAULT CURRENT FOR 0-25 s.



TIME INTERVAL 0.005 s

REPORT No. 2423/3776/1.



Information Centre Knowledge Services [dstl] Porton Down, Salishury Withs SP4-0.IQ 22060-6218 Tel: 01980-613753 Fax-01980-613970

Defense Technical Information Center (DTIC) 8725 John J. Kingman Road, Suit 0944 Fort Belvoir, VA 22060-6218 U.S.A.

AD#: AD355388

Date of Search: 23 June 2008

Record Summary: ADM 227/2335

Title: Fault Carrying Capacity of Santon 200 Amp Admiralty Type Rotary Switch Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years

Former reference (Department) Report No. 2423/3776/1

Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (http://www.nationalarchives.gov.uk) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967.

The document has been released under the 30 year rule.

(The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as <u>UNLIMITED</u>.